



GREISINGER electronic **GmbH**

Operating Manual Precision Barometer

from Version 1.0

GPB 3300









GREISINGER electronic GmbH

D - 93128 Regenstauf, Hans-Sachs-Straße 26

phone: +49 9402 / 9383-0, fax: +49 9402 / 9383-33, eMail: info@greisinger.de

Content

1	1 INTENDED USE	3
2	2 GENERAL ADVICE	3
3	3 SAFETY INSTRUCTIONS	
4		
5		
	5.1 DISPLAY ELEMENTS	
	5.2 PUSHBUTTONS	
6	6 STARTING	4
7	7 MIN-/MAX- VALUE MEMORY	4
8	8 ZERO-FUNCTION (RELATIVE MEASURING)	4
9	GENERAL INFORMATION ON ABSOLUTE PRESSURE MEASUREMENT	4
1(10 CONFIGURATION OF THE DEVICE	5
11	11 ADJUSTING OF THE INSTRUMENT	6
12	12 NOTES TO THE CALIBRATION SERVICES	6
13	13 ERROR AND SYSTEM MESSAGES	6
14	14 SPECIFICATION	
	15 DISPOSAL NOTES	

1 Intended use

The device measures the absolute pressure of air or non corrosive / non ionizing gases.

Relative measurements can also be realized via the integrated Zero-function.

Field of application

- Barometric measurements (weather)
- Over- / Under- pressure measurements

etc...

The safety instruction (see chapter 3) have to be observed.

The device must not be used for purposes and under conditions for that the device had not been designed.

The device must carefully dealt with and has to be used according to the specifications (do not throw, knock, etc.). It has to be protected against dirt.

2 General advice

Read through this document attentively and make yourself familiar to the operation of the device before you use it. Keep this document in a ready-to-hand way in order to be able to look up in the case of doubt.

3 Safety instructions

This device has been designed and tested in accordance to the safety regulations for electronic devices.

However, its trouble-free operation and reliability cannot be guaranteed unless the standard safety measures and special safety advises given in this manual will be adhered to when using it.

- 1. Trouble-free operation and reliability of the device can only be guaranteed if it is not subjected to any other climatic conditions than those stated under "Specification".
 - Transporting the device from a cold to a warm environment condensation may result in a failure of the function. In such a case make sure the device temperature has adjusted to the ambient temperature before trying a new start-up.
- 2. Whenever there may be a risk whatsoever involved in running it, the device has to be switched off immediately and to be marked accordingly to avoid re-starting. Operator safety may be a risk if:
 - there is visible damage to the device or the device is not working as specified
 - the device has been stored under unsuitable conditions for a longer time In case of doubt, please return device to manufacturer for repair or maintenance.
- 3. **Warning:** Do not use this product as safety or emergency stop device, or in any other application where failure of the product could result in personal injury or material damage. Failure to comply with these instructions could result in death or serious injury and material damage.

4 Operation and Maintenance

- If the symbol "LOBAT" is displayed at the left side of display, the battery is weak, measuring can be continued for a short period. If "bAt" is displayed in the main display the battery is used up and needs to be replaced. Measuring is no more possible.
- The battery has to be removed, when storing device above 50 °C.

Hint: We recommend removing the battery if device is not used for a longer period of time! Risk of leakage

5 Operation

5.1 Display elements



1: Main display Display of current measuring value or of minimal measured value ("Lo" blinking) or

maximal value ("Hi" blinking)

LOBAT Indicates low battery

5.2 Pushbuttons



on/off switch, press key long to switch device off **press short**: changes between actual measuring

value, the minimal measured value ("Lo" blinking) and

maximal measured ("Hi" blinking) value. **press >2s:** reset Min and Max value

zero: press >2s: activates / deactivates the "Zero-function"

on/off





6 Starting

Switch the device on with button



After the segment test (RBBB) the device displays some information to its current configuration:

OFF5, if offset correction is active 5CRL, if scale corrections active

Unit of meas. value: nbAr (=mbar) | nnHg (=mmHg)

5ER.L, if sea-level correction is active

P.oFF, if auto power-off is active

Afterwards the device is ready for measuring.

7 Min-/max- value memory

Display MIN-value (Lo): Press button mode shortly Display MAX-value (Hi): Press mode shortly again Display actual value again: Press mode shortly again

Display changes between 'Lo' and min-value Display changes between 'Hi' and max-value

ress mode shortly again Actual value is displayed

Delete MIN/MAX: Press button mode for 2 s MIN&MAX are de

MIN&MAX are deleted. 'CLr' (Clear) is displayed

shortly

The Min-/max- display is automatically set to actual value display after 10 s.

The Min-/max- values are deleted if the device is switched on after it had been turned off.

8 Zero-function (relative measuring)

With help of the Zero-function relative measurements can be realized: press "zero"-button for 2s. "nULL" is displayed shortly and the displayed value is set to 0. Press again "zero" for 2s to display the absolute value again.

Note: Setting and resetting the Zero function will delete your min-/max- value memory.

Field of application: Over/ Under pressure measurement, please mind the measuring range!

9 General information on absolute pressure measurement

The device measures the absolute pressure. This must not be confused with the pressure at sea level display by weather stations. There the pressure loss due to height above sea level is deducted. The device is also able to perform this sea-level correction on the displayed air pressure. Therefore 5ER.L (Sea Level correction) has to be activated (= "on") and the current height above sea level (RLE) = Altitude in [m]) has to be entered at the configuration.

10 Configuration of the device

Follow these instruction to configure the functions of the device:

- Switch the device off.
- Press **mode** button and keep it pressed. Turn the device on. Release the mode button after the segment test (\$\sum_{18.8.8.8}\$) finished. The first parameter "P.oFF" is displayed.
- If a parameter should be changed press key up or down () the present setting of the parameter will be shown and can be changed via up/down keys.

The parameter setting is confirmed by pressing

Jump to the next parameter with

Jump to the next parameter with				
Parameter	value	information		
button on/off	buttons mode zero			
	Auto Power-Off (turn-off delay) factory setting: 20 min.			
P.oFF	ı 120	Auto Power-Off (turn-off delay) in minutes. If no key is pressed for the time adjusted in this parameter, the device is automatically switched off to safe battery power. (adjustable range 1 to 120 min)		
	oFF	automatic power-off is deactivated (continuous operating)		
	Unit and range of display factory setting: nbar = mbar			
Unit	nbAr	300.0 1100.0 mbar, resolution 0.1 mbar		
	nnHG	225.0 825.0 mmHG, resolution 0.1 mmHG		
SER.L	Sea-level correction factory setting: off			
	oFF	Sea-level correction off		
	on	Sea-level correction on		
S	Altitude input for s	ea-level correction factory setting: 340		
ALLI	-500 9000	-500 9000 m selectable		
	Restore to factory settings			
Init	no	Settings are kept		
	YES	Restoring device to factory settings		



again stores the settings, the instruments restarts (segment test)

Please note:

If there is no key pressed within the menu mode within 2 minutes, the configuration will be cancelled, the entered settings are lost!

11 Adjusting of the instrument

To adjust the instruments according to your needs proceed like follows:

- Switch instrument off.
- Press **zero** button and keep it pressed. Turn the device on. Release the mode button after the segment test (1888) finished. The first parameter "5cL" is displayed.
- If a parameter should be changed press key up or down () the present setting of the parameter will be shown and can be changed via up/down keys.

on/off

The parameter setting is confirmed by pressing



Jump to the next parameter with

Parameter	value	information
button	buttons	
on/off	mode zero	
OFFS	Offset of sensors factory setting: off	
0,, 5	oFF -5.0 +5.0	Selectable -5.0 +5.0
SCAL	Scale correction	factory setting: off = 0%
	oFF -5.00 +5.00	Adjustment in %

Pressing on/off

again stores the settings, the instruments restarts (segment test)

Please note:

If there is no key pressed within the menu mode within 2 minutes, the adjusting will be cancelled, the entered settings are lost!

12 Notes to the calibration services

Calibration certificates - DKD-certificates - other certificates:

If device should be certificated for its accuracy, it is the best solution to return it with the referring sensors to the manufacturer. (please state desired test values, e.g. 1bar abs)

Only the manufacturer is capable to do efficient recalibration if necessary to get results of highest accuracy!

13 Error and system messages

Frr 1	r. 1 measuring range has been exceeded	
Err. 2	measured value has fallen below permitted range	
Err. 3	display range has been exceeded (>19999)	
Err. 4	r. 4 measuring value has fallen below displayable range (< -1999)	
Err. 7	System fault - the device has detected a system fault (defective or far outside allowable	
	ambient temperature range)	
	Sensor error or value could not be calculated	

If the symbol "LOBAT" is displayed at the left side of display, the battery is weak, measuring can be continued for a short time.

If "bAt" is displayed in the display the battery is used up and needs to be replaced. Measuring is no more possible.

14 Specification	
Measuring range air pressure:	300.0 1100.0 mbar abs., resolution: 0.1 mbar 225.0 825.0 mmHg abs., resolution: 0.1 mmHg
Measuring media	non corrosive gases
Max. overload:	4000 mbar abs.
Accuracy: (±1 digit)	+/- 2.0 mbar (typ. at 0-50°C)
Pressure connection:	sensor integrated in device
Measuring frequency:	1 measurement per second
Offset and scale:	digital offset and scale adjustment for air pressure measurement
Min-/max-value memory:	min- and max- value are stored
Sea level correction:	The displayed value can be referenced to sea level. Therefore the
	current height above sea level has to be entered.
Zero-function:	relative measurement: the displayed value is set to "zero"
Display:	approx. 13 mm high, 41/2-digit LCD display
Pushbuttons:	3 membrane keys for on/off, min-/max-value request, offset adjustment
Working conditions:	-25 to 50 °C; 0 to 80 % RH (non condensing)
Storage temperature:	-25 to 70 °C
Power supply:	9V-battery, typ. 6F22 (included in scope of delivery)
Current consumption:	ca. 60 µA (Operating time with standard zinc-carbon battery >5000
	hours
Display for weak battery:	automatically if battery consumed "BAT", warning: "LOBAT"
Auto-off function:	If activated: device will be automatically switched off if not operated for
	longer time (selectable 1120min)
Housing:	impact resistant ABS housing, front side IP65
Dimensions:	approx. 106 x 67 x 30 mm (H x W x D), without connecting nozzle
Weight:	approx. 135g incl. battery
EMC:	The device corresponds to the essential protection ratings established in the Directives of the European Parliament and the soundil on the
	in the Directives of the European Parliament and the council on the
	approximation of the laws of the member states relating to the
	electromagnetic compatibility (2004/108/EG). Additional error: <1%

15 Disposal notes



Dispense exhausted batteries at destined gathering places. This device must not be disposed as "residual waste".

To dispose this device, please send it directly to us (adequately stamped).

We will dispose it appropriately and environmentally friendly.